

**AIR MONITORING TEST COMPLETED BY, I. H. SERVICES, INC.
FOR
WISE AVENUE FIRE HOUSE**

Crystal Clean Air, a distributor for MagneGrip Systems by Clean Air Concepts, installed a MagneGrip exhaust venting system for the Wise Avenue Fire House in the City of Baltimore Maryland. After the installation was completed, Wise Avenue had I H Services, Inc. come out to the fire house for an air quality test.

Warren Billingsley, the hygienist, met Dave Martini from the fire house, and Dave McLaughlin from Crystal Clean Air. The hygienist monitored the air for CO and O₂ while the MagneGrip exhaust venting system was attached to the trucks. Readings were taken near the trucks in both garage areas and the hallway on the first floor. The 2nd floor area in the stairwell and above the garage were also sampled, and a reading was taken six inches from the exhaust of a truck. Fifteen readings in total were taken at the request of fire house personnel.

The results are attached on the following 3 pages.

I H SERVICES, INC.

1831 Portal Street — Suite E • Baltimore, Maryland 21224



REPORT OF ANALYSIS

Main Office
410-633-4000
Fax
410-633-4122

4-048
WISE AVE. FIRE HOUSE
214 Wise Ave.
Baltimore, MD 21222

TIME	CO	O ₂	Location of Reading
1024	0	20.8	G
1030	0	20.8	A
1035	0	20.9	B
1040	0	20.8	C
1045	0	20.7	D
1050	0	20.7	E
1055	0	20.9	F
1100	0	20.9	G
1104	0	20.7	H
1105	0	20.7	A
1110	0	20.9	B
1115	0	20.9	C
1120	0	20.9	D
1125	0	20.8	E
1130	0	20.9	F



I H SERVICES, INC.

1831-E Portal Street • Baltimore, Maryland 21224

PHONE:
(410) 633-4000FAX:
(410) 633-4122

DAILY OBSERVATIONS

Page 1 of 2DATE: February 12 2004INSPECTOR: Warren BillingsleySITE: Wise Ave. Fire HouseTITLE: Industrial Hygienist214 Wise Ave.Baltimore, MD 21222


PURPOSE OF VISIT:

Air monitoring for CO, and O₂.

GENERAL OBSERVATIONS:

Hygienist on site to meet Dave Martini from fire house, and Dave McLaughlin from MagneGrip Crystal Clean Air. Hygienist monitor air for CO, and O₂ while exhaust venting system on trucks are tested. Readings are taken by trucks in both garage areas and hallway on first, 2nd floor area in stairwell and above garage was also sampled, also reading was taken six inches from exhaust of truck. Fifteen readings in total are taken at the request of fire house personnel.

Wise Ave Fire House



Front ©